



**WASTE MANAGEMENT
OF CANADA CORPORATION**

2301 Carp Road
Carp, ON K0A 1L0
(613) 831-1281
(613) 831-8928 Fax

January 15, 2009

Mr. Greg Davis
Ontario Ministry of the Environment
Ottawa District Office
2430 Don Reid Drive
Ottawa, Ontario,
K1H 1E1

**Re: WM Ottawa Waste Management Facility – Quarterly Report – October 1,
2008 – December 31, 2008.**

Dear Mr. Davis,

As per Condition 2 of the Provincial Officer's Order 7160-79THQR, Waste Management of Canada Corporation has prepared a report that details all odour contingency plan activities for the period of October 1, 2008 to December 31, 2008.

Enclosed Flares

The two (2) enclosed flares were fully operational throughout the reporting period. The flares were shut down from time to time to conduct maintenance. The flares were restarted as soon as the maintenance work was completed in order to reduce the shut down time.

We have received a C of A to operate the temporary flare on October 1, 2008. The temporary flare will be used until the landfill gas to energy (LFGTE) facility starts operation. This flare is required to ensure proper flaring capacity as we are adding more landfill gas (LFG) wells to the collection system.

Landfill Gas (LFG) Collection System

The LFG Collection System was monitored on a daily basis. The LFG field was balanced on a weekly basis by WMCC technicians. The data collected was entered into the Landfill Gas Management System (LGMS) for analysis by the LFG operations manager.

No new LFG wells were installed during the period. As of the end of December 31, 2008, the LFG Collection System consisted of 158 LFG wells.

We have also started the installation of an electrical system and a dewatering system to install pumps in the LFG wells on the North and South Slopes. This will help to optimize the LFG Collection System.

Capping

A total of about six hectares of final capping was completed during the reporting period. The capping was completed on the North, West and South Slopes. Daily cover was applied to the working face and interim cover was applied to zones where landfilling would not take place over the following month.

Cap Inspection

The landfill slopes were inspected on a daily basis and repairs were scheduled. Repairs were conducted when the area could be safely accessed.

Beanie Capping on top of the Landfill Footprint

The beanie cap design was completed by Comcor Environmental. An application was submitted to MOE on March 31/08 for their approval. The final Certificate of Approval for the beanie cap was released by MOE on December 10/08.

Emission Survey

Two air emission surveys were conducted in early November and December. The sampling for the October survey was delayed to early November due to improper weather conditions. The reports for the surveys have been sent to MOE and posted on WMCC website.

Planned Construction and/or maintenance activities report

The planned construction and/or maintenance activities reports were posted on the WMCC website on the first day of each month.

We are available to meet with you to discuss any additional questions or concerns you may have.

Yours truly,



Rémi Godin, P.Eng.

Sr. District Engineer – Eastern Canada