



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries:

1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/01/07	8AM		10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	NW 3KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080107/8:40AM/OLF2186
08/01/07	9:30AM		10 OUT OF 10	HWY 417	Y	NO WIND	Y	Y	NO WIND	080107/1:42PM/OLF2176
08/01/07	9:30PM	DRIVE BY	10 OUT OF 10	CARP ROAD	Y	SSW 15KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080207/7PM/OLF2155
08/01/07	9:40PM		6 OUT OF 10	CARP ROAD AT THE LIGHTS?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED (WHICH SET OF LIGHTS?)	080107/9:58PM/OLF2162
08/01/07	9:56AM		10 OUT OF 10	CARDEVCO ROAD, CARP	Y	SW 13KM	Y	Y	INQUIRY LOCATED NNW FROM SITE; WIND BLOWING NE	080107/10:50AM/OLF2180
08/01/07	9?		10 OUT OF 10	DRIVE BY	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	080107/9:58PM/OLF2165
08/01/07	9?	DRIVE BY	5 OUT OF 10	HUNTMAR AND OLD CARP	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	080307/3:06PM/OLF2244
08/02/07	4:50PM		10 OUT OF 10	AT THE CARP ROAD EXIT OFF 417	Y	SSW 24KM	Y	Y	INQUIRY LOCATED E OF SITE; WIND BLOWING NNE	080307/3:06PM/OLF2245
08/02/07	5:30PM	DRIVE BY	8 OUT OF 10	DRIVING NORTH ALONG CARP ROAD	Y	SSW 19KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080407/9:12AM/OLF2238
08/02/07	8PM	DRIVE BY	7 OUT OF 10	DRIVING UP RICHARDSON SIDE ROAD WESTBOUND	Y	SSW 15KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080207/11:03PM/OLF2153
08/02/07	9:15AM		5 OUT OF 10	RICHARDSON SIDE ROAD	Y	SW 8KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080207/9:33PM/OLF2154
08/03/07	4:35PM	DRIVE BY	4 OUT OF 10	417 WEST BOUND CARP ROAD EXIT	Y	W 21KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/4:58PM/OLF2243
08/03/07	5:15PM		9 OUT OF 10	GETTING OFF THE 417 AT CARP ROAD	Y	W 21KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/9:57PM/OLF2239
08/03/07	5:39PM	DRIVE BY	5 OUT OF 10	HWY 417 WEST OF CARP ROAD	Y	WSW 13KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/9:57PM/OLF2240



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/03/07	5:42PM		3 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 18KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/9:57PM/OLF2242
08/03/07	7PM	1 HOUR	8 OUT OF 10	CARP EXIT	Y	W 16KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080407/11:46PM/OLF2237
08/03/07	8AM		3 OUT OF 10	THUNDERBIRD - RICHARDSON SIDE ROAD	Y	SSW 5KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/3:06PM/OLF2247
08/03/07	9AM		10 OUT OF 10	AT THE SITE; FRONT ENTRANCE	Y	SW 11KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080307/3:06PM/OLF2246
08/04/07	7:53?		7 OUT OF 10	KIMPTON DR	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	080407/11:46PM/OLF2236
08/04/07	8:30PM		8 OUT OF 10	CARP AND 417	Y	W 6KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080407/11:46PM/OLF2235
08/04/07	9:18PM	DRIVE BY	7 OUT OF 10	DRIVING ON CARP ROAD TO CARP FROM HAZELDEAN ROAD	Y	WSW 5KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080407/11:46PM/OLF2234
08/04/07	9PM		9 OUT OF 10	CARP ROAD NEAR HWY 417	Y	WSW 3KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080507/10:58AM/OLF2249
08/05/07	6AM		10 OUT OF 10	AMETHYST CRES, STITTSVILLE	Y	W NO WIND	Y	Y		080507/10:58AM/OLF2251
08/05/07	7:07AM		7 OUT OF 10	WILDERNESS WAY, STITTSVILLE	Y	WNW NO WIND	Y	Y		080507/10:58AM/OLF2250
08/05/07	7AM	ALL NIGHT	9 OUT OF 10	417 NEAR CARP ROAD	Y	WNW NO WIND	Y	Y		080507/10:58AM/OLF2248
08/05/07	8:15AM	13 HOURS	5 OUT OF 10	WILLIAM MOONEY DRIVE	Y	NNE 2KM	Y	Y	INQUIRY LOCATED WNW FROM SITE; WIND BLOWING SSW	080507/10:38PM/OLF2253
08/07/07	6:30PM	ALL EVENING	6 OUT OF 10	MY RESIDENTS	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	080707/9:56PM/OLF2298
08/07/07	7:29AM		10 OUT OF 10	WILLOWLEA ROAD	Y	N 3KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080707/9:29AM/OLF2254
08/08/07	11:15AM	ALL MORNING	10 OUT OF 10	WILLOWLEA ROAD	Y	WNW 23KM	Y	Y	INQUIRY LOCATED SSE FROM SITE; WIND BLOWING ESE	080807/4:53PM/OLF2302

Q2 ODOR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007

E & OE

WM Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/08/07	11:15AM	4 HOURS	2 OUT OF 10	WILLOWLEA ROAD	Y	WNW 23KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080807/4:53PM/OLF2305
08/08/07	4PM	ALL AFTERNOON	10 OUT OF 10	WILLOWLEA ROAD	Y	NW 19KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080807/4:53PM/OLF2304
08/08/07	6:27AM		7 OUT OF 10	CRANTHAM CRESCENT, STITTSVILLE	Y	WSW 8KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ENE	080807/7:33AM/OLF2300
08/08/07	6:30AM		7 OUT OF 10	CRANTHAM CRES TO WESTRIDGE, HAZELDEAN AND THEN NORTH ON CARP ROAD	Y	WSW 8KM	Y	Y	CAPPING WITH CLAY ON THE NORTH SLOPE WAS COMPLETED. LEACHATE SEEPS WERE REPAIRED ON THE NORTH SLOPE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM. THE COLLECTION SYSTEM WAS REMOVED TO PLACE WASTE ON THE SW SLOPE.	080807/9:10PM/OLF2301
08/08/07	6:50AM		8 OUT OF 10	ALON STREET	Y	WSW 8KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING ENE	080807/4:53PM/OLF2303
08/08/07	7:40?	DRIVE BY	7 OUT OF 10	HUNTMAR & 417	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	080907/5:58PM/OLF2308
08/09/07	11:35AM		8 OUT OF 10	PENNYCROSS LANE, CARP	Y	ESE 11KM	Y	Y	INQUIRY LOCATED WSW FROM SITE; WIND BLOWING WNW	081007/6:40AM/OLF2309
08/09/07	6:03AM	ALL MORNING	10 OUT OF 10	MCEWAN'S GAS BAR ON CARP ROAD	Y	NE 3KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING SW	080907/8:12AM/OLF2307
08/09/07	6:35AM		10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	NE 6KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING SW	080907/8:12AM/OLF2306
08/10/07	10:12AM	3 HOURS	9 OUT OF 10	MCLENNAN WAY AND SCOTIABANK PLACE	Y	NE 11KM	Y	Y	INQUIRY LOCATED ENE FROM SITE; WIND BLOWING SW	081107/12:06AM/OLF2329
08/10/07	10:25AM		8 OUT OF 10	CAMPEAU DRIVE - 12 FLOOR	Y	NNE 11KM	Y	Y	INQUIRY LOCATED NNE FROM SITE; WIND BLOWING SSW	081107/12:06AM/OLF2330
08/10/07	10PM	1 HOUR	5 OUT OF 10	INSMILL CR	Y	SSW 5KM	Y	Y	LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/3:37PM/OLF2323
08/10/07	5:35AM		10 OUT OF 10	MCLENNAN WAY, KANATA	Y	NE 6KM	Y	N	INQUIRY LOCATED SEVERAL KM'S ENE FROM SITE; WIND BLOWING SW; MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	081007/8:43PM/OLF2331
08/10/07	6:41AM		5 OUT OF 10	WILDMEADOW CIRCLE, CARP	Y	ENE 5KM	Y	Y	LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081007/12:24PM/OLF2299
08/11/07	11AM		3 OUT OF 10	MCEWAN'S GAS BAR ON CARP ROAD	Y	W 16KM	Y	Y	LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081207/8:12AM/OLF2316
08/11/07	4:30PM		6 OUT OF 10	BLACKBIRD LANE	Y	W 16KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	081107/11:24PM/OLF2321
08/11/07	6:55?		6 OUT OF 10	ON MY FRONT STEPS?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081307/12:29PM/OLF2336
8/11/2007	7PM	ALL EVENING	8 OUT OF 10	AT THE CORNER OF CAMPEAU DRIVE & EAGLESON	Y	W 6KM	Y	Y	INQUIRY LOCATED SEVERAL KM'S ENE FROM SITE; WIND BLOWING E	081407/7:40AM/OLF2342
08/11/07	8:03AM	ALL MORNING	8 OUT OF 10	HAPEL CRES	Y	W 16KM	Y	Y	CANNOT LOCATE ADDRESS INDICATED	081107/3:37PM/OLF2328
08/11/07	8:07AM		10 OUT OF 10	JACKSON TRAILS DEVELOPMENT (NEAR STITTSVILLE MAIN STREET NORTH OF HAZELDEAN ROAD)	Y	W 16KM	Y	Y	INQUIRY LOCATED 3.5 KM ESE FROM SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/3:37PM/OLF2327
08/11/07	8:10AM		7 OUT OF 10	AMBERWOOD	Y	W 16KM	Y	Y	INQUIRY LOCATED 4 KM ESE FROM SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/3:37PM/OLF2325
08/11/07	8:30AM		8 OUT OF 10	BROWNS YIG	Y	W 18	Y	Y	INQUIRY LOCATED 3.5 KM SE FROM SITE; WIND BLOWING E	081107/3:37PM/OLF2326
08/11/07	9:05AM	ALL MORNING	6 OUT OF 10	JACQUELINE CRES, STITTSVILLE	Y	W 16KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	081107/3:37PM/OLF2324

Q2 ODOUR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007

E & OE



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/11/07	9:10AM		7 OUT OF 10	MACEWANS GAS BAR	Y	W 11KM	Y	Y	INQUIRY LOCATED 1.5 KM SE FROM SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081307/3:20PM/OLF2339
08/11/07	9:54PM		7 OUT OF 10	CAMPEAU DRIVE - 12 FLOOR	Y	SW 10KM	Y	Y	INQUIRY LOCATED 5.5 KM NE FROM SITE. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/11:25PM/OLF2318
08/11/07	9AM		10 OUT OF 10	OVERLAND DRIVE AND KIMPTON (JACKSON TRAILS)	Y	W 16KM	Y	Y	INQUIRY LOCATED 3 KM SE OF SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/11:25PM/OLF2317
08/11/07	9AM		10 OUT OF 10	OVERLAND DRIVE & KIMPTON (JACKSON TRAILS)	Y	W 16KM	Y	Y	INQUIRY LOCATED 3 KM SE OF SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/11:24PM/OLF2319
08/11/07	9AM		10 OUT OF 10	OVERLAND DRIVE & KIMPTON (JACKSON TRAILS)	Y	W 16KM	Y	Y	INQUIRY LOCATED 3 KM SE OF SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/11:24PM/OLF2320
08/11/07	9AM		10 OUT OF 10	OVERLAND DRIVE & KIMPTON (JACKSON TRAILS)	Y	W 16KM	Y	Y	INQUIRY LOCATED 3 KM SE OF SITE WIND BLOWING E. LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081107/11:24PM/OLF2322
08/11/07	9PM		6 OUT OF 10	CARP ROAD (417 TO LAURYSSEN KITCHENS)	Y	SW 8KM	Y	Y	LFG WELLS WERE RECONNECTED ON THE SW SLOPE AFTER COMPLETING THE INSTALLATION OF THE LFG COLLECTION SYSTEM.	081207/8:12AM/OLF2315
8/12/2007	1PM	DRIVE BY	10 OUT OF 10	CARP ROAD & 417	Y	SW 18KM	Y	Y	INQUIRY LOCATED ENE FROM SITE; WIND BLOWING NE	081407/7:40AM/OLF2341
08/12/07	4:30?		9 OUT OF 10	HWY 7 AND HAZELDEAN ROAD	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	081207/5:09PM/OLF2313
08/12/07	6:08AM		6 OUT OF 10	KIMPTON DRIVE, STITTSVILLE	Y	SW 8KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NE	081207/9:30PM/OLF2312
08/12/07	8:30PM	1 HOUR	10 OUT OF 10	CARP ROAD EXIT GOING TOWARDS RICHARDSON SIDE ROAD	Y	SW 11KM	Y	Y		081307/7:10AM/OLF2311
08/12/07	ALL MORNING		7 OUT OF 10	HELM CIRCLE, STITTSVILLE?	Y		Y	Y	CANNOT LOCATE ADDRESS INDICATED	081207/1:22PM/OLF2314
08/13/07	10:52PM		6 OUT OF 10	LLOYDALEX CRESCENT	Y	NW 27KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081307/11:27PM/OLF2343
08/13/07	11:32AM		7 OUT OF 10	CARP ROAD & 417	Y	WNW 24KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081370/12:29PM/OLF2338
08/13/07	3:20PM	2 HOURS	10 OUT OF 10	WILLOWLEA ROAD	Y	W 44KM	Y	Y	INQUIRY LOCATED SSE FROM SITE; WIND BLOWING E	081377/7:47PM/OLF2348
08/13/07	6:20AM		10 OUT OF 10	DELAMERE DRIVE	Y	WNW 6KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081307/7:10AM/OLF2310
08/13/07	6:42PM	2 HOURS	8 OUT OF 10	OZDOME OPTICS	Y	W 18KM	Y	Y	INQUIRY LOCATED SSE FROM SITE; WIND BLOWING E	8/13/7/8:56PM/OLF2345
08/13/07	7:02PM	ALL EVENING	7 OUT OF 10	CRANTHAM CRESCENT, STITTSVILLE	Y	WNW 18KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081307/7:47PM/OLF2347
08/13/07	7:15AM	1 HOUR	5 OUT OF 10	HOME?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081307/8:29AM/OLF2335
08/13/07	7:35AM		8 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	W 10KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	081307/8:29AM/OLF2334
8/13/2007	7PM	ALL EVENING	8 OUT OF 10	STONEPATH CRES, STITTSVILLE	Y	WNW 18KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ESE	081407/7:40AM/OLF2340
08/13/07	8:06PM	ALL EVENING	3 OUT OF 10	ALONG THE BICYCLE PATH IN TIMBERMERE, ALSO ALONG SIDE THE CARP ROAD/417	Y	WNW 10KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081307/8:34PM/OLF2346

Q2 ODOUR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

E & OE

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSTY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/13/07	8:13AM	DRIVE BY	8 OUT OF 10	CARP ROAD & HAZELDEAN ROAD	Y	WNW 18KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081307/8:29AM/OLF2333
08/13/07	8:30AM	2 HOURS	6 OUT OF 10	HOME?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081307/12:29PM/OLF2337
08/13/07	8PM	EVENING	8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 15KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ESE	081307/11:27PM/OLF2344
08/14/07	10:59AM	1 HOUR	7 OUT OF 10	RICHARDSON SIDE ROAD	Y	SW 8KM	Y	Y	INQUIRY LOCATED NNE FROM SITE; WIND BLOWING NE	081507/4:39AM/OLF2351
08/14/07	5:30PM	1 HOUR	5 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SE 8KM	Y	Y	INQUIRY LOCATED WNW FROM SITE; WIND BLOWING NW	081407/8:51PM/OLF2356
08/14/07	6:30AM	2 HOURS	10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	WSW 8KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ENE	081407/12:23PM/OLF2349
08/14/07	6:30AM		6 OUT OF 10	OVERLAND & KIMPTON (JACKSON TRAILS)	Y	WSW 8KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081407/7:40AM/OLF2350
08/14/07	6:30PM		7 OUT OF 10	WILLIAM MOONEY DRIVE/HUNTLEY MANOR	Y	SE 8KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081407/8:51PM/OLF2358
08/14/07	7:45PM		8 OUT OF 10	AT MY NEXT DOOR NEIGHBOURS?	Y	ESE 11KM	Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081407/8:51PM/OLF2357
08/14/07	8:40PM		6 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SE 8KM	Y	Y	INQUIRY LOCATED WNW FROM SITE; WIND BLOWING NW	081407/8:51PM/OLF2355
08/14/07	8:43PM	ALL EVENING	8 OUT OF 10	WILBERT COX DRIVE	Y	SE 8KM	Y	Y	INQUIRY LOCATED WNW FROM SITE; WIND BLOWING NW	081407/8:51PM/OLF2353
08/14/07	8:43PM	ALL EVENING	8 OUT OF 10	WILBERT COX DRIVE	Y	SE 8KM	Y	Y	INQUIRY LOCATED WNW FROM SITE; WIND BLOWING NW	081407/8:51PM/OLF2354
08/15/07	0830?	2 HOURS	10 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	81607/2:46PM/OLF2393
08/15/07	10AM	ALL MORNING	4 OUT OF 10	PLAYGROUND ON WESTRIDGE DRIVE	Y	W 19KM	Y	Y	INQUIRY LOCATED 3 KM SE FROM SITE; WIND BLOWING E	081507/8:19PM/OLF2362
08/15/07	10PM		10 OUT OF 10	CARP ROAD IN FRONT OF SITE	Y	WNW 3KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081507/11:29PM/OLF2359
08/15/07	5PM	ALL NIGHT	7 OUT OF 10	WHALINGS CIRCLE JACKSON TRAILS DEVELOPMENT (NEAR STITTSVILLE MAIN STREET NORTH OF HAZELDEAN ROAD)	Y	WNW 24KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81707/1:13PM/OLF2400
08/15/07	6AM		8 OUT OF 10	OUTSIDE MY HOUSE?	Y	SW 10KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NE	081507/12:56PM/OLF2372
08/15/07	7:30PM		7 OUT OF 10		Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081507/12:56PM/OLF2371
08/15/07	7PM		7 OUT OF 10	BLACKBIRD LANE	Y	NW 16KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081507/10:31PM/OLF2361
08/15/07	8:30AM		10 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 24KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081507/12:57PM/OLF2369
08/15/07	8:30PM?	ALL EVENING	7 OUT OF 10	RANDALL JAMES DRIVE, STITTSVILLE	Y		Y	Y	NO DATA FROM WEATHER STATION. TIME IS IN FUTURE. IT WAS SENT VIA EMAIL AT 4:39AM AND WAS REPORTED AS 8:30PM???	081507/4:39AM/OLF2352
08/15/07	8AM	ALL MORNING	10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	W 19KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	081507/12:57PM/OLF2370

Q2 ODOUR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007

E & OE



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSTIY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/15/07	9:30PM		9 OUT OF 10	ON CARP ROAD BETWEEN THE 417 AND HAZELDEAN ROAD	Y	WNW 2KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081507/10:31PM/OLF2360
08/15/07	9AM		10 OUT OF 10	WESTBROOK ROAD	Y	WNW 18KM	Y	Y	INQUIRY LOCATED SSE FROM SITE; WIND BLOWING ESE	8/15/7/12:57PM/OLF2368
08/16/07	1:16PM		4 OUT OF 10	STAPLES IN KANATA	Y	SW 30KM	Y	Y	INQUIRY LOCATED 4.5 KM ENEFROM SITE WIND BLOWING NE	8/16/7/1:27PM/OLF2366
08/16/07	1:17PM		4 OUT OF 10	STAPLES IN KANATA	Y	SW 30KM	Y	Y	INQUIRY LOCATED 4.5 KM ENEFROM SITE WIND BLOWING NE	81607/1:27PM/OLF2394
08/16/07	1:30PM		10 OUT OF 10	AT THE CARP ROAD EXIT FROM 417 TO LIGHTS	Y	SW 30KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081907/11:32AM/OLF2407
08/16/07	1:35PM		10 OUT OF 10	AT THE ENTRANCE TO THE CARP LANDFILL AT THE LIGHTS AT INTERSECTION TO 417	Y	SW 30KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81907/11:32AM/OLF2403
08/16/07	10:10AM		8 OUT OF 10	IN MY BACKYARD?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	081707/6:47AM/OLF2373
08/16/07	10:10AM		9 OUT OF 10	ON THE CARP ROAD INFRONT OF THE SITE AND UP TO HAZELDEAN ROAD	Y	SSW 10KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081707/6:47AM/OLF2376
08/16/07	11:05?	DRIVE BY	8 OUT OF 10	417?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	82307/1:15PM/OLF2449
08/16/07	11:30AM		9 OUT OF 10	NEWCASTLE AVE (MORGAN'S GRANT) KANATA	Y	SSW 18KM	Y	Y	INQUIRY LOCATED 6 KM NNE FROM SITE.	081607/11:37AM/OLF2363
08/16/07	12:35PM	DRIVE BY	6 OUT OF 10	CARP ROAD FROM THE DUMP TO RICHARDSON SIDE ROAD	Y	SW 26KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	08/16/7/1:27PM/OLF2367
08/16/07	12:35PM	DRIVE BY	6 OUT OF 10	CARP ROAD FROM THE SITE TO RICHARDSON SIDE ROAD	Y	SW 26KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81607/1:27PM/OLF2395
08/16/07	1PM		6 OUT OF 10	SCOTIA BANK PLACE	Y	SW 30KM	Y	Y	INQUIRY LOCATED SEVERAL KMS DOWNWIND FROM SITE	81707/8:47AM/OLF2380
08/16/07	2:30PM		10 OUT OF 10	SCOTIA BANK PLACE	Y	WSW 16KM	Y	Y		81607/6:57PM/OLF2390
08/16/07	3:15PM	2 HOURS	9 OUT OF 10	CARP ROAD, STITTSVILLE	Y	SW 19KM	Y	Y	INQUIRY LOCATED 3 KM SE FROM SITE; WIND BLOWING NE	81707/1:24PM/OLF2398
08/16/07	4:28PM	ALL AFTERNOON	8 OUT OF 10	CRANTHAM CRESCENT, STITTSVILLE	Y	WNW 29KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81607/4:44PM/OLF2392
08/16/07	4:30PM		10 OUT OF 10	AT THE LIGHTS IN FRONT OF THE FACILITY	Y	WNW 29KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081907/11:32AM/OLF2406
08/16/07	4:35PM		10 OUT OF 10	AT THE LIGHTS AT CARP ROAD EXIT FROM 417	Y	WNW 29KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081907/11:32AM/OLF2405

Q2 ODOUR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007

E & OE



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSTY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/16/07	4:37PM		9 OUT OF 10	HORSEWORLD ON CARP ROAD	Y	WNW 29KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81607/4:44PM/OLF2391
08/16/07	5PM	ALL DAY	9 OUT OF 10	DELAMERE DRIVE	Y	WNW 24KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ESE	081707/6:47AM/OLF2374
08/16/07	5PM	ALL NIGHT	7 OUT OF 10	WHALINGS CIRCLE	Y	WNW 24KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ESE	81707/1:13PM/OLF2399
08/16/07	6:15PM	4 HOURS	10 OUT OF 10	CARP ROAD FROM HAZELDEAN TO THE ON RAMP GOING WEST ON THE 417	Y	WNW 20KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81707/6:47AM/OLF2379
08/16/07	7:30PM		7 OUT OF 10	STITTSVILLE PUB ON MAIN STREET	Y	NNW 9KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING SSE	8/17/7/6:47AM/OLF2377
08/16/07	7:51PM	ALL EVENING	8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	NO WIND	Y	Y	NO WIND	81607/11:35PM/OLF2387
08/16/07	7AM	DRIVE BY	5 OUT OF 10	ON RICHARDSON RD BETWEEN WILLIAM MOONEY AND CARP ROAD	Y	SSE 6KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081607/10:36AM/OLF2365
08/16/07	8:29PM	ALL EVENING	7 OUT OF 10	KIMPTON DRIVE	Y	NO WIND	Y	Y	NO WIND	81607/11:35PM/OLF2385
08/16/07	8:30PM		8 OUT OF 10	LONE MEADOW	Y	NO WIND	Y	Y	NO WIND	81607/11:35PM/OLF2384
08/16/07	8:31PM	ALL EVENING	8 OUT OF 10	KIMPTON DRIVE	Y	NO WIND	Y	Y	NO WIND	081607/11:35PM/OLF2383
08/16/07	8:37AM		9 OUT OF 10	KIMPTON DRIVE (JACKSON TRAILS)	Y	SSE 8KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NNW	81607/11:35PM/OLF2386
08/16/07	8:37AM		9 OUT OF 10	KIMPTON DRIVE (JACKSON TRAILS)	Y	SSE 8KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NNW	81607/11:35PM/OLF2389
08/16/07	8AM		8 OUT OF 10	WESTHUNT DRIVE, CARP	Y	S 8KM	Y	Y		081707/8:47AM/OLF2381
08/16/07	8AM	ALL DAY		LADYBIRDS CRES, STITTSVILLE	Y	S 8KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING N	81607/11:35PM/OLF2388
08/16/07	8AM	8 HOURS	10 OUT OF 10	WILLOWLEA ROAD	Y	S 16KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING N	81707/1:47PM/OLF2402
08/16/07	8AM	DRIVE BY	6 OUT OF 10	2020 RICHARDSON SIDE ROAD	Y	SSE 11KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	82007/8:47PM/OLF2404
08/16/07	8PM		8 OUT OF 10	OVERLAND DRIVE & KIMPTON (JACKSON TRAILS)	Y	NW 11KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING SE.	081707/6:47AM/OLF2375
08/16/07	9:27AM		8 OUT OF 10	STITTSVILLE MAIN STREET PUB AND HAZELDEAN ROAD	Y	S 13KM	Y	Y	INQUIRY LOCATED 4 KM SE FROM SITE; WIND BLOWING N	081707/6:47AM/OLF2378
08/16/07	9:27AM		8 OUT OF 10	STITTSVILLE MAIN STREET AND HAZELDEAN ROAD	Y	S 13KM	Y	Y	INQUIRY LOCATED 3 KM ESE FROM SITE; WIND BLOWING N	081607/11:35PM/OLF2382
08/16/07	9:54PM		6 OUT OF 10	ON HAZELDEAN ROAD FROM IBER TO STITTSVILLE MAIN STREET	Y	WSW 10KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING ENE	81607/9:54PM/OLF2396
08/16/07	9AM		5 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SSE 10KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	081607/11:10AM/OLF2364
08/17/07	7:40AM		2 OUT OF 10	KIMPTON DRIVE (JACKSON TRAILS)	Y	W 13KM	Y	Y	CAPPING WITH COMPACTED CLAY WAS COMPLETED ON THE SOUTH SLOPE. PUMPS WERE INSTALLED IN THE LFG WELLS ON THE NW SLOPE. LFG WELLS WERE INSTALLED ON THE NORTH SLOPE ABOVE THE SOIL PAD AND AT THE NE CORNER OF THE LANDFILL FOOTPRINT.	81707/8:01AM/OLF2397
08/17/07	8:43AM		5 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	W 19KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	81707/11:12AM/OLF2401
08/17/07	9:30PM		8 OUT OF 10	ROGERS VIDEO CARP AND MAIN STREET, STITTSVILLE	Y	W 21KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	8/22/7/7:22AM/OLF2410
08/18/07	3:30PM	2 HOURS	9 OUT OF 10	PALLADIUM AUTO PARK	Y	WNW 26KM	Y	Y	INQUIRY LOCATED ENE FROM SITE; WIND BLOWING ESE	81907/9:21AM/OLF2422
08/18/07	8?		8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y		Y	Y	UNKNOWN TIME OF DAY AM/PM?	81907/9:21AM/OLF2421
08/19/07	6:03AM		7 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	NW 9KM	Y	Y		81907/9:21AM/OLF2418



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/19/07	6:30AM	1 HOUR	7 OUT OF 10	DELAMERE DRIVE	Y	NW 9KM	Y	Y		82007/8:47PM/OLF2420
08/19/07	6:45AM		8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	NW 13KM	Y	Y		81907/9:21AM/OLF2416
08/19/07	7AM		9 OUT OF 10	BLACKBIRD LANE	Y	NW 13KM	Y	Y		81907/9:21AM/OLF2417
08/19/07	9:26AM		7 OUT OF 10	TIMBERMERE SUBDIVISION	Y	N 11KM	Y	Y		81907/11:32AM/OLF2419
08/20/07	8:30PM		6 OUT OF 10	WILBERT COX DRIVE	Y	ESE 5KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	8/21/7/1:36PM/OLF2415
08/20/07	8AM		5 OUT OF 10	RICHARDSON SIDE ROAD	Y	E 2KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82007/8:47PM/OLF2414
08/21/07	6:15AM		7 OUT OF 10	WILBERT COX DRIVE	Y	NE 6KM	Y	Y	INQUIRY LOCATED W FROM SITE; WIND BLOWING SW	82307/4:24PM/OLF2447
08/21/07	6:45AM		9 OUT OF 10	HUNTMAR & MAPLE GROVE	Y	E 3KM	Y	Y	INQUIRY LOCATED ENE FROM SITE; WIND BLOWING W	82107/7:32AM/OLF2413
08/21/07	7AM	ALL MORNING	10 OUT OF 10	HUNTMAR & MAPLE GROVE	Y	ENE 5KM	Y	Y	INQUIRY LOCATED ENE FROM SITE; WIND BLOWING WSW	82107/9:30AM/OLF2412
08/22/07	1:17AM	ALL MORNING	6 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SSE 9KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82207/1:59PM/OLF2443
08/22/07	6:44PM	ALL EVENING	6 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	ESE 5KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82207/8:06PM/OLF2425
08/22/07	6:45AM		9 OUT OF 10	NORTHSHIRE DRIVE, CARP	Y	E 13KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	082207/7:22AM/OLF2409
08/22/07	6AM	ALL DAY	4 OUT OF 10	NORTHSHIRE DRIVE, CARP	Y	E 6KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82407/7:04AM/OLF2445
08/22/07	7:15AM		8 OUT OF 10	NORTHSHIRE DRIVE, CARP	Y	E 13KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82207/8:01AM/OLF2411
08/22/07	8:23AM	ALL MORNING	8 OUT OF 10	RUSHING BROOK DRIVE	Y	E 13KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	082207/8:38AM/OLF2408
08/23/07	1:30PM	DRIVE BY	8 OUT OF 10	RICHARDSON SIDE ROAD / CARP ROAD	Y	S 8KM	N	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED. HYDRO ON SITE; FLARE NOT OPERATIONAL DUE TO SAFETY REASONS	82407/6:01AM/OLF2446
08/23/07	1:35AM	ALL NIGHT	8 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SE 3KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82307/8:19AM/OLF2424
08/23/07	11:35PM	DRIVE BY	7 OUT OF 10	CARP ROAD TO RICHARDSON SIDE ROAD	Y	SSW 11KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82407/5:28PM/OLF2441
08/23/07	4:30PM		7 OUT OF 10	WILBERT COX DRIVE	Y	S 8KM	Y	Y	INQUIRY LOCATED W FROM SITE; WIND BLOWING NNE.	82407/7:04AM/OLF2444
08/23/07	5:48AM		7 OUT OF 10	WILBERT COX DRIVE	Y	SE 7KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	82307/4:24PM/OLF2448
08/23/07	7:30AM	ALL MORNING	7 OUT OF 10	RICHARDSON SIDE ROAD	Y	SE 5KM	Y	Y	INQUIRY LOCATED NNE FROM SITE; WIND BLOWING NW	82307/1:15PM/OLF2450
08/23/07	8:12AM	ALL DAY	9 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	ESE 16KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82307/8:24AM/OLF2423
08/23/07	8AM		6 OUT OF 10	MY HOUSE?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	82307/9:32AM/OLF2442
08/24/07	1:25PM	DRIVE BY	7 OUT OF 10	CARP ROAD IN FRONT OF THE SITE TO RICHARDSON SIDE ROAD	Y	SW 11KM	N	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED. HYDRO ON SITE; FLARE NOT OPERATIONAL DUE TO SAFETY REASONS	82407/5:28PM/OLF2439
08/24/07	10:22pm		4 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	SW 6KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NE	82507/9:01AM/OLF2437
08/24/07	12:45PM	1 HOUR	4 OUT OF 10	PARKING LOT CANADIAN TIRE KANATA	Y	SW 18KM	Y	Y	INQUIRY LOCATED SEVERAL KM'S DOWNWIND FROM SITE	82407/5:28PM/OLF2440

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSITY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/24/07	5:04PM	DRIVE BY	4 OUT OF 10	417 WEST BOUND AT CARP ROAD	Y	WSW 18KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82507/9:01AM/OLF2438
08/24/07	6:45PM	3 HOURS ALL EVENING	7 OUT OF 10	CARP ROAD 417 /RICHARDSON SIDE ROAD	Y	SW 11KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82507/10:50AM/OLF2435
08/24/07	8PM		10 OUT OF 10	FRANK NIGHBOR PLACE	Y	SW 6KM	Y	Y	INQUIRY LOCATED 4.5 KM'S NE FROM SITE	82507/9:01AM/OLF2436
08/24/07	9:45PM		6 OUT OF 10	ON HWY 417 BETWEEN THE PALLADIUM DRIVE EXIT AND THE CARP ROAD EXIT	Y	SW 6KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82807/11:38PM/OLF2456
08/25/07	8:30PM	DRIVE BY	8 OUT OF 10	DRIVING ON CARP ROAD FROM CARP TO HAZELDEAN ROAD	Y	W 8KM	Y	Y	LFG WELLS WERE CONNECTED TO THE LFG COLLECTION SYSTEM ON THE WEST SLOPE. LEACHATE SEEPS ON THE SW SLOPE WERE REPAIRED.	82607/6:58PM/OLF2434
08/26/07	10:30PM		9 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	NW 8KM	Y	Y		82607/11:47PM/OLF2426
08/26/07	10AM		7 OUT OF 10	CARP ROAD ALL THE WAY FROM 417 TO CRANTHAM CRES	Y	NW 16KM	Y	Y		82607/11:47PM/OLF2427
08/26/07	3PM		6 OUT OF 10	BLACKBIRD LANE	Y	W 15KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	82607/6:58PM/OLF2433
08/26/07	6:39AM		5 OUT OF 10	417 ON RAMP EAST BOUND	Y	W 15KM	Y	Y		82607/7:48PM/OLF2431
08/26/07	7:30PM	DRIVE BY	8 OUT OF 10	HAZELDEAN ROAD ALL THE WAY FROM CARP ROAD TO KEVIN HAIME DRIVING RANGE (BETWEEN TERRY FOX AND IBER ROAD)	Y	W 8KM	Y	Y		82607/11:47PM/OLF2429
08/26/07	7:36AM		4 OUT OF 10	JACKSON TRAILS DEVELOPMENT (NEAR STITTSVILLE MAIN STREET NORTH OF HAZELDEAN ROAD)	Y	W 15KM	Y	Y		82607/7:48PM/OLF2432
08/26/07	7:55AM	ALL MORNING	10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	W 13KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	82707/12:30PM/OLF2478
08/26/07	7:55PM	DRIVE BY	10 OUT OF 10	417 AND CARP ROAD	Y	W 8KM	Y	Y		82607/11:47PM/OLF2430
08/26/07	8:37PM		10 OUT OF 10	417 AT CARP ROAD	Y	W 11KM	Y	Y		82707/12:30PM/OLF2470
08/26/07	8PM	1 HOUR	8 OUT OF 10	OVERLAND AND KIMPTON (JACKSON TRAILS)	Y	WSW 8KM	Y	Y	INQUIRY LOCATED E OF SITE; WIND BLOWING ENE	82607/11:47PM/OLF2428
08/26/07	9:30PM		10 OUT OF 10	BLACKBIRD LANE	Y	WNW 8KM	Y	Y		82707/11:27PM/OLF2465
08/27/07	10PM	ALL EVENING	10 OUT OF 10	RICHARDSON SIDE ROAD-CARP ROAD-417	Y	SE 3KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82807/8:03AM/OLF2462
08/27/07	11:10PM	ALL EVENING	10 OUT OF 10	417-CARP ROAD-RICHARDSON SIDE ROAD	Y	SSE 6KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	82807/8:03AM/OLF2460
08/27/07	11:40PM	ALL EVENING	10 OUT OF 10	WILBERT COX DRIVE	Y	SSE 6KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	82807/8:03AM/OLF2461
08/27/07	6:30AM		7 OUT OF 10	BRIGHTSIDE AVE, STITTSVILLE	Y	W 3KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E	82707/8:14AM/OLF2452
08/27/07	6:35AM	2 HOURS	5 OUT OF 10	BEECHFERN DR, STITTSVILLE	Y	SSW NO WIND	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNE	82707/12:30PM/OLF2472
08/27/07	6:35AM		8 OUT OF 10	OVERLAND & KIMPTON (JACKSON TRAILS)	Y	SSW NO WIND	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NNE	82707/8:14AM/OLF2453
08/27/07	7:11AM	ALL MORNING	7 OUT OF 10	KIMPTON DRIVE (JACKSON TRAILS)	Y	WNW NO WIND	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/8:14AM/OLF2451
08/27/07	7:11AM	ALL MORNING	7 OUT OF 10	KIMPTON DR (JACKSON TRAILS)	Y	WNW NO WIND	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2477
08/27/07	7:35AM		7 OUT OF 10	AMBERWOOD VILLAGE	Y	S 2KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING N	82707/2:40PM/OLF2466
08/27/07	7:40AM	ALL MORNING	5 OUT OF 10	KITTIWAKE DRIVE ALONG THE WAY TO MAIN STREET STITTSVILLE	Y	SSW 2KM	Y	Y	INQUIRY LOCATED SE; WIND BLOWING NNE	82707/12:30PM/OLF2480
08/27/07	7:47AM		10 OUT OF 10	HESSE CRES, STITTSVILLE	Y	WSW NO WIND	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ENE	82707/12:30PM/OLF2471
08/27/07	7:55AM	ALL MORNING	10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	WSW NO WIND	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING ENE	82707/12:30PM/OLF2469
08/27/07	7AM		9 OUT OF 10	BLACKBIRD LANE	Y	SW NO WIND	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NE	82707/11:27PM/OLF2464
08/27/07	7AM		10 OUT OF 10	WALGREEN RD	Y	SW NO WIND	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NE	82707/12:30PM/OLF2474
08/27/07	8:24AM		8 OUT OF 10	DELAMERE DRIVE	Y	NW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2475
08/27/07	8:28AM		7 OUT OF 10	FRONT DOOR ?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	82707/12:30PM/OLF2467

Q2 ODOUR INQUIRY SUMMARY REPORT ENDING AUGUST 31, 2007

E & OE



Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries:

1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSTIY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/27/07	8:30AM	ALL MORNING	6 OUT OF 10	WESTRIDGE ROAD	Y	NW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/11:27PM/OLF2463
08/27/07	8:32AM		9 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	NW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2468
08/27/07	8AM		10 OUT OF 10	DELAMERE DRIVE	Y	NW 2KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2473
08/27/07	8AM		10 OUT OF 10	WALGREEN RD AT WESTBROOK	Y	NW 2KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2476
08/27/07	8AM		10 OUT OF 10	WALGREEN ROAD	Y	NW 2KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82707/12:30PM/OLF2479
08/28/07	12:44PM	DRIVE BY	10 OUT OF 10	AT THE GATE ENTRANCE AT THE CARP ROAD FACILITY	Y	SSW 6KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/7:45PM/OLF2510
08/28/07	5:30PM		9 OUT OF 10	CHESHIRE CAT PUB, RICHARDSON AND CARP ROAD	Y	S 15KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82807/7:56PM/OLF2459
08/28/07	6PM	1 HOUR	8 OUT OF 10	CHESHIRE CAT PUB, RICHARDSON AND CARP ROAD	Y	S 10KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82807/7:56PM/OLF2458
08/28/07	7:30PM	DRIVE BY	7 OUT OF 10	CARP ROAD/417 TO RICHARDSON	Y	S 6KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82907/9:04AM/OLF2481
08/28/07	8:30AM		3 OUT OF 10	IN FRONT OF MY HOUSE?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	82807/11:38PM/OLF2457
08/28/07	8:30PM		8 OUT OF 10	CARP ROAD?	Y		Y	Y	NO MUNICIPAL ADDRESS SUPPLIED	82907/6:57AM/OLF2454
08/28/07	9AM	ALL DAY	7 OUT OF 10	RICHARDSON SIDE ROAD	Y	SSW 2KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82907/6:57AM/OLF2455
08/29/07	10:03PM		9 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/12:14AM/OLF2484
08/29/07	10:03PM		9 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/12:14AM/OLF2489
08/29/07	10:30PM		9 OUT OF 10	CHESHIRE CAT PUB, RICHARDSON AND CARP ROAD	Y	SE 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/7:54AM/OLF2488
08/29/07	10:41PM	1 HOUR	4 OUT OF 10	HUNTLEY MANOR DRIVE, CARP	Y	SE 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/3:19PM/OLF2495
08/29/07	10PM		8 OUT OF 10	BLACKBIRD LANE	Y	WNW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/12:14AM/OLF2485
08/29/07	10PM		8 OUT OF 10	BLACKBIRD LANE	Y	WNW 5KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/12:14AM/OLF2490
08/29/07	3:45PM	DRIVE BY	6 OUT OF 10	DRIVE BY	Y	SSW 19KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82907/5:02PM/OLF2483
08/29/07	3:45PM	DRIVE BY	6 OUT OF 10	CARP ROAD PAST THE SITE	Y	SSW 19KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	82907/5:02PM/OLF2492
08/29/07	4:30PM	DRIVE BY	9 OUT OF 10	CARP ROAD NORTH OF 417	Y	SSW 23KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/3:19PM/OLF2496
08/29/07	5:20PM	1 HOUR	8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	SSW 19KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNE	82907/7:50PM/OLF2486
08/29/07	5:20PM	1 HOUR	8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	SSW 19KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNE	82907/7:50PM/OLF2491
08/29/07	6PM		10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	NW 10KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/7:54AM/OLF2487
08/29/07	7:47AM		6 OUT OF 10	RICHARDSON SIDE ROAD	Y	SSW 8KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	8/29/7/9:04AM/OLF2482
08/30/07	10:44AM		5 OUT OF 10	FLEWELLYN RD, STITTSVILLE	Y	NNW 18KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/12:22AM/OLF2509
08/30/07	11:15AM	ALL AFTERNOON	10 OUT OF 10	WILLOWLEA ROAD	Y	S 6KM	Y	Y	INQUIRY LOCATED SSE FROM SITE; WIND BLOWING N	83007/3:19PM/OLF2493
08/30/07	11:30AM	ALL DAY	9 OUT OF 10	WILLOWLEA ROAD	Y	NW 19KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83007/3:19PM/OLF2494
08/30/07	11:50PM	ALL NIGHT	8 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	WNW 16KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	83107/12:22AM/OLF2507
08/30/07	5AM	DRIVE BY	3 OUT OF 10	HWY 417 AND CARP ROAD	Y	NW 15KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	83107/6:28PM/OLF2514
08/30/07	9:35PM		5 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	NW 6KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/12:22AM/OLF2508
08/31/07	11:50PM		4 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	N 15KM	Y	N	INQUIRY LOCATED SE; WIND BLOWING S; MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	917/2:19AM/OLF2512

WM Ottawa Waste Management Facility
2301 Carp Road, Carp ON K0A 1L0

Total Inquiries: 1272

ODOUR EMAIL NOTIFICATION INFORMATION						WASTE MANAGEMENT NOTIFICATION & RESPONSE				
DATE	TIME	DURATION	ODOUR TYPE/ INTENSTY	LOCATION (residence/place of business)	RECEIVED VIA EMAIL (Yes/No)	WIND DIRECTION DATA WM WEATHER STATION (FROM) SPEED KM/HR	LFG OPERATIONAL SYSTEM STATUS (Yes/No) COLLECTION & FLARE MISTING SYSTEM		OPERATIONAL UPDATES/COMMENTS	Email Received Date/Time/Email Record #
08/31/07	4AM	2 HOURS	10 OUT OF 10	SNOWY OWL TRAIL, STITTSVILLE	Y	W 2KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	83107/10:37AM/OLF2501
08/31/07	5AM	DRIVE BY	7 OUT OF 10	HWY 417 AND CARP ROAD	Y	W 16KM	Y	N	MISTING SYSTEM NOT OPERATIONAL BETWEEN 11PM-6AM	83107/6:28PM/OLF2513
08/31/07	6:30AM		9 OUT OF 10	AMBERWOOD VILLAGE	Y	WNW 6KM	Y	Y		90307/8:33PM/OLF2511
08/31/07	6:50AM		8 OUT OF 10	TIMBERMERE SUBDIVISION	Y	SE 2KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NW.	83107/6:28PM/OLF2515
08/31/07	6:53AM	ALL MORNING	9 OUT OF 10	SIROCCO CRES, STITTSVILLE	Y	SSE 3KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNW.	83107/7:07AM/OLF2505
08/31/07	6:55AM		9 OUT OF 10	DENHAM WAY, STITTSVILLE	Y	SSE 3KM	Y	Y	INQUIRY LOCATED ESE FROM SITE; WIND BLOWING NNW.	83107/7:07AM/OLF2506
08/31/07	7:30AM		4 OUT OF 10	KITTIWAKE DRIVE	Y	W 16KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING E.	83107/10:37AM/OLF2497
08/31/07	7:47AM		7 OUT OF 10	OVERLAND & KIMPTON (JACKSON TRAILS)	Y	WNW 2KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/7:58AM/OLF2504
08/31/07	7AM	4 HOURS	10 OUT OF 10	CRANTHAM CRES	Y	SSE 3KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNW.	83107/10:37AM/OLF2499
08/31/07	7AM		9 OUT OF 10	ECHO POND WAY	Y	SSE 3KM	Y	Y	INQUIRY LOCATED SE FROM SITE; WIND BLOWING NNW.	83107/8:19AM/OLF2502
08/31/07	8:05AM		10 OUT OF 10	LADYBIRDS CRES, STITTSVILLE	Y	WNW 3KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/10:37AM/OLF2500
08/31/07	8AM		9 OUT OF 10	BLACKBIRD LANE	Y	WNW 3KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/10:37AM/OLF2498
08/31/07	8AM	ALL MORNING	9 OUT OF 10	KIMPTON DRIVE, JACKSON TRAILS	Y	WNW 3KM	Y	Y	LFG WELLS ON THE SE SLOPE WERE CONNECTED TO THE LFG COLLECTION SYSTEM.	83107/8:19AM/OLF2503